VISIBLE EMISSION NOTA	TIONS		_	
Inspector: RICK PAL	OMO			
Date of Inspection:) [
Shift: 1 st Shift or 2 nd Sh	ift Ti 2nd	me: 5:00 AM		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments 1	
Visible Emission From Shaker	NOR	**************************************		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATI	IONS			
Inspector: PICK P	ALOMO			
Date of Inspection: 4/3/10	:			
Shift: 1 st Shift or 2 nd Shift	end	me: 5: 00 AM		
	Visual Inspection NORMAL of ABNORMAL		Comments.	
Visible Emission From Shaker	NOR	+ ye-work der		
Visible Emission From Discharge Conveyor System	NOR	and the second second second second		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS				
Inspector: $\mathcal{K}\mathcal{U}$	ve Itea				
	-4-11				
Shift: (1st Shift or 2nd St	nift Time	1710			
Unit	Visual Inspection NORMAL of ABNORMAL		Comment	The second of th	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector: RCK	ALOMO			
Date of Inspection:	4/11			
Shift: 1 st Shift or 2 nd S	hift d Ti 2nd	me: 5200 AM		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	* most register all and resident and property and propert		
Visible Emission From Discharge Conveyor System	Nor	** With the result of the section of		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS				
Inspector:	SIFE -				
Date of Inspection:	-5-11				
Shift: (1 st Shift or 2 nd Sh	nift Ti	me: (7/0			
Unit	Visual Inspection <u>NOR</u> MAL or "ABNORMAL		Comm	nents	
Visible Emission From Shaker	ior				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: 6 / Jan	,			
Date of Inspection:	15/11			
Shift: 1 st Shift or 2 nd Sh	nift Ti	me: 0500		
Unit Control of the Control of the C	Visual inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	Non	ушнайть		
Visible Emission From Discharge Conveyor System	NON	materia.		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
	GITE			
	6-11			
Shift: (1 st Shift or 2 ^{hd} Sh	nift Ti	ime: 1710		
Unit (Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nov	nderdeten statut bereitste det eine der der der der der der der der der de		
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Date of Inspection: Unit Visual Inspection NORMAL Or ABNORMAL	VISIBLE EMISSION NOT	ATIONS				· ·
Shift: 1st Shift or zed Shift Time: Unit Visual Comments Inspection NORMAL Or ABNORMAL	Inspector:					
Unit Visual Comments Inspection NORMAL Or ABNORMAL	4/6	[11				
Inspection. NORMAL Or ABNORMAL	Shift: 1 st Shift or 2 ^{pd} Sh	nift Ti	ime: <i>CoS</i> 00			
or <u>ABN</u> ORMAL	Unit	Inspection				
		or				
Visible Emission From Shaker	Visible Emission From Shaker			(General Company) in the second secon	ta Aliani ka ta ta da kuman kutu da ka ta	
Visible Emission From Discharge Conveyor System Vol		Noh	Thingsof .			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector: 5- GUZIZ	endo			
Date of Inspection:				
Shift: 1 st Shift or 2 nd Si	hift SECOND T	me: 52M		
	Visual Inspection NORMAL		Comments:	
	<u>ABN</u> ORMAL			
Visible Emission From Shaker	NOV			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT.	ATIONS				
Inspector: K.Wa	Iter				
Date of Inspection:	7-11				
Shift: 1st Shift or 2nd S	hift Ti	me: /7/0			
unit	Visual Inspection NORMAL		Comments	and a second of the second	
	ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS					
Inspector:	· · · · ·					
Date of Inspection:	18/11				-	
Shift: 1 st Shift or 2 nd Sf	Ti Ti	me: Cospo				
+ Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL			nents		
Visible Emission From Shaker	Nor	Физичейна				
Visible Emission From Discharge Conveyor System	Non	уудордага				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTAT	IONS			
Inspector: Ted Cox	npton			
Date of Inspection: 4/9///	Ú			
Shift: 1 st Shift or 2 nd Shift	Time:	5:00 AM		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: Ted Compton	
Date of Inspection: 4/10/11	
Shift: 1st Shift or 2nd Shift Time: 5:00 Am	
Unit Visual Inspection NORMAL OF ABNORMAL	Comments
Visible Emission From Shaker	
Visible Emission From Discharge Conveyor System	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	VISIBI	F	FN	IISS	ION	NO.	ΓΑΊ	TION
----------------------------	--------	---	----	------	-----	-----	-----	------

Inspector: R Long				
Date of Inspection:	0/11			
Shift: Shift or 2 nd Sh		Time: 5 pm		
Establishment (1997) Unite	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background,

VISIBLE EMISSION NOTA	ATIONS		-	
Inspector:				
Staly	nel			
Date of Inspection:	4/11/11			
Shift: 1 st Shift or (2 nd Sh	nift Ti	me: 0520		
Unit	Visual Inspection		Comments	
Property of the Control of the Contr	<u>NOR</u> MAL or			
	<u>ABN</u> ORMAL			
Visible Emission From Shaker	Nac			
Visible Emission From				·
Discharge Conveyor System	Non	; interestablishin		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: (1st Shift or 2nd Shift Time: Unit Visual Comments Inspection NORMAL ABNORMAL Visible Emission From Shaker NOR Visible Emission From NOR Discharge Conveyor System

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- **Opacity** is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	TIONS		_	
Inspector: RICK PA	LOMO			
Date of Inspection: 4/12	2/11	_		
Shift: 1 st Shift or 2 nd Sh	ift Ti	me: 5:00 AM		
Unit (1)	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR	. And the state of		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBLE FIMISSION NOTA	TIONS			
Inspector: R Long				
Date of Inspection: 4/17	111			
Shift: 1 st Shift or 2 nd Sh	ilft Ti	me: 5-pm		
Unit	ya Visual		. Comments	
	Inspection <u>NOR</u> MAL			
	or <u>Abn</u> ormal			
Visible Emission From Shaker	NOR			
Visible Emission From				
Discharge Conveyor System	NOR			


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: RICK PA	Lare			
Date of Inspection:	3/11			
Shift: 1 st Shift or 2 nd Sh	ift end Ti	me: 5:00 AM		
Unit:	Visual Inspection <u>NOR</u> MAL Of <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	**************************************		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: (st Shift or Time: Unit Visual Comments Inspection NORMAL **ABN**ORMAL Visible Emission From Shaker NOR Visible Emission From Discharge Conveyor System NOR

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS

FIGURE ZIMOGRAFITA			
Inspector:			
Date of Inspection:			
Shift: 1 st Shift or 2 nd Shift	Time:	-	
Unit Visu Inspec NORN or ABNOR	tion IAL	Comments	
Visible Emission From Shaker Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

TIONS					
4///					
ift Tin	ne: 5pm				
Visual			Comments		
<u>NORMAL</u>					
or <u>ABN</u> ORMAL					-
Nor					
NOR					
	Visual Inspection NORMAL or	Visual Inspection NORMAL or	Visual Inspection NORMAL or	Visual Comments Inspection NORMAL or	Visual Comments Inspection NORMAL or

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

VISIBLE EMISSION NOTA	ATIONS				
Inspector: R Lon					
Date of Inspection:	5/11				
Shift: 1 st Shift or 2 nd Sh	ift Ti	me: 50M			
Unit	Visual		Comments		
	Inspection NORMAL OF				
Visible Emission From Shaker	ABNORMAL NOR		· · · · · · · · · · · · · · · · · · ·		
Visible Emission From Discharge Conveyor System	NOR				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: (1st Shift or Shift: Time: Unit Visual Comments Inspection NORMAL **ABNORMAL** Visible Emission From Shaker Non Visible Emission From Discharge Conveyor System Noz

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift


(Stack SDS 04)

Inspector:	PI	CK PAC	Lond	
Date of Inspe		4/19/11		
Shift: 1 st Si	hift or	2 nd Shift	Time: 5300	

	1 W.		j		
Unit	Visual		Comments		
	Inspection				
a constitution of the cons	NORMAL				
	or			•	
	<u>ABN</u> ORMAL				
Visible Emission From Shaker	NOR				
Visible Emission From					
Discharge Conveyor System	NOR	*c_missionschiptschiptschinerkomförstpattigengen			


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- **Opacity** is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS



VISIBLE EMISSION NOTA	ATIONS			
Inspector: R Lon	re,			
Date of Inspection: 4/2	0/11			
Shift: 1° Shift or 2005	nift Ti	me: 5pm		
Unit	Visual Inspection		Comments	
	<u>NORMAL</u>			
A TOTAL CONTROL OF THE CONTROL OF TH	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTA	ATIONS			
Inspector: R Long				
Date of Inspection: 4/2	(1)	\$1		
Shift: 151 Shift or 2 nd Sh	ift Ti	me: Spm		
Unit	Visual Inspection		Comments	
	<u>NORMAL</u> or			
Visible Emission From Shaker	ABNORMAL NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

Inspector: RICK PAC	OMO				
Date of Inspection: 4/22	/11				
Shift: 1 st Shift or 2 nd SI	nift Ti	ime: 5,00			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL		C	omments	
Visible Emission From Shaker	NOR	, and the contract of the cont			
Visible Emission From Discharge Conveyor System	NOR	and the second s			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS				
Inspector: R Low	9				
Date of Inspection: 4/2	2/11			•	
Shift: (1 st Sh)ft or 2 nd Sh	ift Ti	me: 5pm			
Unit	Visual		Comments		
	Inspection NORMAL				,
	or <u>ABN</u> ORMAL		The second secon		
Visible Emission From Shaker	NOR				
Visible Emission From	,				
Discharge Conveyor System	NOR				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector: Sam &	auzizrdo)		
Date of Inspection: 4/23	1117			
Shift: 1 st Shift or 2 nd Si	SECOND TI	me: SAM		
Unit	Visual		Comments	
	Inspection <u>NORMAL</u> or			
The state of the s	<u>ABN</u> ORMAL		ki s	
Visible Emission From Shaker	NOR		· Processing and an extraction with the second and an extraction of the second and an extraction of the second	
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- **Opacity** is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Alexand	Im II erna	nde2		
Date of Inspection:	73-11			
Shift: 1 st Shift or 2 nd Sh		e: 5pm		
Unit	Visual		Comments	
	Inspection NORMAL or ABNORMAL			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Date of Inspection: Shift: 1st Shift or cross Shift: Time: Costo Unit: Visual Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From Discharge Conveyor System NORMAL OF ABNORMAL Visible Emission From Discharge Conveyor System	VISIBLE EMISSION NOTA	ATIONS			
Date of Inspection: Shift: 1 st Shift or Parish Time: Comments Unit: Visual Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From	Inspector:				
Unit Visual Inspection Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From		24/11			
Visual Inspection Inspection NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From	Shift: 1st Shift or Sh	nift Ti	me: 0500		
NORMAL or ABNORMAL Visible Emission From Shaker Visible Emission From	Unit			Comments	
Visible Emission From		<u>NORMAL</u> or			
	Visible Emission From Shaker	Mn	·		
		Non			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS					
Inspector: Ale works	Hernande	2				
Date of Inspection: 4-21	<u>}- \\</u>					
Shift: 1 st Shift or 2 nd Sh	nift Ti	me: 5DW				
Unit	Visual			Comments		
	Inspection <u>NORMAL</u> or					
The state of the s	ABNORMAL		•	****	 	
Visible Emission From Shaker	NOR					
Visible Emission From Discharge Conveyor System	NOR					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight

(Stack SDS 04)

VISIBLE EMISSION NOTA	ATIONS		_			
Inspector: RICK PAL	OMO					
Date of Inspection: 4/25	/11					
Shift: 1 st Shift or 2 nd Sh	nift Ti	ime: 5300				
Unit	Visual Inspection			Comments		
	<u>NORMAL</u> or <u>ABN</u> ORMAL		<u> </u>		,	1
Visible Emission From Shaker	NOR					
Visible Emission From Discharge Conveyor System	Nor	-december of the contract of t				 ·

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack

AIRIBLE FIM	ISSION NO	AHO	N2		
Inspector:	$\overline{\Omega}$				

Date of Inspection: 4/75-//

Shift: 1 st Shift or 2 nd Sh	nift 7	Time: 5	pM				
Unit	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL				Comments		
Visible Emission From Shaker	Non						
Visible Emission From Discharge Conveyor System	ron						

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS		_			
Inspector:						
Date of Inspection:	26/11					
Shift: 1 st Shift or (2 ^{nd*} Sh	nift) Ti	ime: @ 0.500				
Unit	Visual			Comments		
	Inspection NORMAL					
The state of the s	or <u>ABN</u> ORMAL			entry .		
Visible Emission From Shaker	Nak	Supplements				
Visible Emission From Discharge Conveyor System	Nat	Marianes.				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

VISIBLE EMISSION NOT	ATIONS				
Inspector: R LONG					
Date of Inspection:	4/26/11				
Shift: 1 Shift or 2 nd Sh	nift Ti	me: 5 pm			
Unit	Visual	1		Comments	
The state of the s	Inspection NORMAL				
	or <u>ABN</u> ORMAL		## * *	and the second s	
Visible Emission From Shaker	Ner				
Visible Emission From Discharge Conveyor System	MOR				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

AISIBFE EMISSION	NOTATIONS	
Inspector: RICK	PALOMO	

Date of Inspection: 4/27/11

Shift: 1st Shift or 2nd Shift

Shift: 1" Shift or 2" Si		me: 5° 00 AM		
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR	Consequinate September 1		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: R Low	9			
Date of Inspection: 4/2	7/11			
Shift: (1 st Shift or 2 ^{nt} Sh	nift Ti	me: 5 pm		
Unit	Visual		Comments	
	Inspection NORMAL			
The state of the s	or ABN ORMAL			•
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

VISIBLE EMISSION NOTA	ATIONS			
Inspector: R Lo	NG			
Date of Inspection:	128/11			
Shift: (1 st Shift or 2 nd Sh	ilft Ti	me: 5-ρm		
Unit	Visual		Comments	
	Inspection NORMAL or ABNORMAL			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

۹.	/ISIRI			100	IOAI	MIO.	TAT	\cap
w		_	ועו דו	1.7.7	IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	171()		にいいつ

Inspector: RICK PAL	OMO			
Date of Inspection: 4/28/	1 (
Shift: 1 st Shift or 2 nd Sh	2nd	me: 5°00 AM		
:Unit	Visual Inspection		Comments	
A Company of the Comp	NORMAL or			
The state of the s	ABNORMAL		<u> </u>	
Visible Emission From Shaker	NOR	and the English of the Control of th		
Visible Emission From Discharge Conveyor System	Norm	- quantinophilistical d		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: ()	
15 Cons	
Date of Inspection: U/29///	
Shift: (1st Shift or 2nd Shift Time:	
Shift: 1st Shift or 2 Shift Time:	
Unit Visual Comments	
Inspection	
<u>NORMAL</u>	
Or ABNORMAL	
Visible Emission From Shaker	
North North	
Visible Emission From	****************
Discharge Conveyor System \(\hat{\chi}\) (\hat{\chi}\)	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

V	ISIBLE	EMISSI	ON NOTATIONS
•			^

Inspector: Rick /	?Alome			
Date of Inspection:	129/11			
Shift: 1 st Shift or 2 nd SI	nift Ti 2nd	ime: 53 00 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOK	And the second s		
Visible Emission From Discharge Conveyor System	Nop			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

VISIBLE EMISSION NOTA	TIONS		_	
Inspector: Ted Co.	mpton			
Date of Inspection:	5/1/			
Shift: 1 st Shift or (2 nd Sh	ift Ti	me: 506AM		
Unit	Visual Inspection		Comments	
A control of an analysis of the second of th	NORMAL			
A first transport of the control of	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Nac	Programme and processing and the state of th		
Visible Emission From	/ N D V			
Discharge Conveyor System	\mathcal{N}_{o}			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE E	EMISSION	I NO	TATIONS	
Inspector:	W.	V	PAI ama	

Date of Inspection:

Shift: 1 st Shift or 2 nd Shi	ift Time	500 Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	5		
Visible Emission From Discharge Conveyor System	Nae	, where the production of the		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.